



## RAM 6 Update from RFAL

Dr. Rodrigo Teixeira  
Principal Scientist  
University of Alabama Huntsville  
(256) 479-6664  
[rodrigo.teixeira@uah.edu](mailto:rodrigo.teixeira@uah.edu)

Mr. Chris Sautter  
Associate Director  
University of Alabama Huntsville  
(256) 824-6147  
[chris.sautter@uah.edu](mailto:chris.sautter@uah.edu)

Mr. Daniel Sillivant  
Reliability Engineer  
University of Alabama Huntsville  
(256) 824-5770  
[daniel.sillivant@uah.edu](mailto:daniel.sillivant@uah.edu)



**CONFIDENTIAL**

***Overview of RFAL approach***  
***Latest results for Chinook and Kiowa***

***Today***

# HUMS Analysis: Current CI Approach

power spectra of component




0.1




0.2




...




CI





# Typical CI Run




# Actionable Information



# Current CI Approach




# Bayesian Methods



Curiosity rover (navigation)



speech recognition



stock trading



reliability

?



***Architecture***


# Top View

spectra




fault probability  
metric

# Sequential Monte Carlo



Stochastic Model  
(engineering physics)







***Chinook***

# Preliminary Results



- *Known Removal*
- *Known Normal*
- *Known NEOF*

# Known Normals



# Known NEOF



Tail 08-3775





# Known Removal

## Tail 04-03740 (Chip Light)



**Craft:** MH-47 04-03740

**Component:** engine transmission



**Part:** #1 nose gearbox, single HUMS sensor

**Action:** transmission removed on May 2<sup>nd</sup>, 2012 for excessive metal contamination (chip light)

**Inspection:** shoulder to a bearing inner race broke in three places causing the rolling elements to degrade and a gear to become chipped.



# MH-47G Aircraft 050375



## Excerpt from the report: “Review of Tear Down Analysis (TDA) of Engine Transmission Serial Number (SN): A11-083DRGI, Removed from MH-47G Aircraft 0503755 (TTS 117836A)”

*Background: The subject component was removed for excessive vibration. Findings: Upon inspection, RTC found abnormal wear patterns on both the input pinion and output bevel gear teeth. The output bevel gear also showed abnormal staining on the inner race of bearing PN 145D603-3. RDMRAEP noted that bearing PN 145DS600-4 exhibited false brinelling on both raceways of its inner and outer races. **RDMR-AEP stated that “due to the lack of significant damage, and since the time horizon to maintenance is > 100 hours, the Component Condition for this Engine Transmission is Green.”***

*Data Analysis: **The component condition does not align with the level of damage suggested by the MSPU.** There are two condition indicators (CIs) designed to detect bearing damage within the #1 engine transmission: Survey FPG100 Engine Xmsn #1 High Freq Energy and Survey FPG100 Engine Xmsn #1 Bearing Energy. While the former CI gave no indication of bearing damage, the latter implied severe damage to the output bevel gear bearings (Appendix A, Figures 1-2). (bolded for emphasis).*

# MH-47G Aircraft 050375





Figure 2: Bearing Energy CI indicating severe bearing damage





## ***Kiowa Blind Study***

## **Problem:**


- Tail rotor gearbox sensor data
- Two datasets: one normal and one fatal accident
- No maintenance logs, actions, tear down analyses, CIs, or any indication of where the abnormality occurred
- Anecdotal evidence given that supported intermittency

## **Solution:**

- Assumption of abnormal signature
- Same algorithm but “retrained” model parameters
- 12 frequencies used (previously 4)



# Consolidated Data Requirements





***End***